

3/015/072



A. Distance view of overburden rmoval at Western Clay Company's gypsum mine, notice UTU-73779 in T.24S., R.7E., Section 23. 4-16-96.



B. Road cut on the access road just west of the gysum mine, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 4-16-96.





5/015/072



C. Access road looking west just west of the gypsum mine, Western Clay Company, Notice UTU-73779 in T.24S., R.7E., Section 23. 4-16-96.



D. Culvert installed on the access road just west of the gypsum mine, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 4-16-96.

